



# 1-1016



Wkręt do drewna z łbem stożkowym,  
z niepełnym gwintem, z gniazdem TORX  
**A2**



<b>dk</b>	6	7	8	9	10	12	14	18
<b>k</b>	1,6	1,8	2,1	2,3	2,8	3,6	4,1	4,7
<b>gniazdo</b>	TX10	TX10	TX20	TX20	TX25	TX25	TX40	TX40

<b>d</b>	3	3,5	4	4,5	5	6	8	10
----------	---	-----	---	-----	---	---	---	----

<b>l</b> 25	500 b=18	500 b=18	500 b=18	500 b=18	500 b=18			
30	500 b=18	500 b=18	500 b=18	500 b=18	500 b=18	100 b=18		
35		500 b=24	500 b=24	500 b=24	500 b=24	100 b=24		
40	500 b=24	200 b=24	200 b=24	200 b=24	200 b=24	100 b=24		
45			200 b=30	200 b=30	200 b=30	100 b=30		
50		200 b=30	200 b=30	200 b=30	200 b=30	100 b=30		
55				200 b=35	200 b=35	100 b=35		
60			200 b=35	200 b=35	100 b=35	100 b=36		100 b=50
70			200 b=42	200 b=42	100 b=40	100 b=42	100 b=50	
80				200 b=50	100 b=50	100 b=48	100 b=50	100 b=55
90					100 b=60	100 b=54	100 b=60	
100					100 b=60	100 b=70	100 b=80	100 b=55
110						100 b=70		
120					100 b=70	100 b=70	100 b=80	100 b=80
130						100 b=70		
140						100 b=70	100 b=80	100 b=80
150						100 b=70		
160						100 b=70	100 b=80	100 b=80
180						100 b=70	100 b=80	100 b=105
200						100 b=70	100 b=80	100 b=105
220						100 b=70	100 b=80	100 b=105
225							100 b=80	
240						100 b=70	100 b=80	100 b=105
260						100 b=70	100 b=80	100 b=105
280						100 b=70	100 b=80	100 b=105
300						100 b=70	100 b=80	100 b=105
320								100 b=105
325							100 b=80	
340								50 b=105
350							100 b=80	
360							100 b=80	50 b=105
375							100 b=80	50 b=105

Ilość szt. w opakowaniu jednostkowym